

IVECO AS440S46 STRALIS ALCOA'S



Itemno 306119
Kind Tractor unit
Specification
Matriculation year 2015 / 03
Mileage 875,399 km

Chassisnumber
WJMM1VTH60C309787

Technical condition

Remarks

(A15)

Price € 12950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 7,978 kg
Gross vehicle weight 18,000 kg
Total fuel capacity 910 litre
2nd fuel tank ✓
Fifth wheel height 116 cm
Diff. locks 1
Wheelbase 360 cm
Aluminium rims ✓
Suspension type air suspension

Cabin

Cabin type High roof
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Parking heater ✓
Color Red

Drivetrain

Engine make Iveco
Engine capacity 338 Kw (459 Hp)
Euro 6
Gearbox kind AS-tronic
Number of Gears 12
Power steering ✓
ABS ✓
ASR ✓

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●○	Good state
●●●○●	Reasonable state
●●○●●	Moderate state
●●○○●	Does not meet requirements