

MERCEDES-BENZ ATEGO 1323 AIRCO TAILLIFT



Itemno 306297
Kind Truck
Specification Closed box
Matriculation year 2019 / 05
Mileage 286,128 km

Chassisnumber
WDB96702610326844

Technical condition
Remarks

(A15)

Price € 39900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 7,186 kg
Gross vehicle weight 13,500 kg
Total fuel capacity 200 litre
Wheelbase 540 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color white
Reversing camera ✓

Drivetrain

Engine capacity 170 Kw (231 Hp)
Euro 6
Gearbox kind Automatic
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 814 cm
Inner box width 248 cm
Inner box height 238 cm
Load bed height 110 cm
Netto height 230 cm

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 1,500 kg
Tail-lift make palgfinger
Tail-lift material aluminium
Tail-lift size 248x182

Tyres/Wheels

Sparewheel ✓
Spare tire profile 12 mm

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Superstructure

Internal condition	●●●●●●●●
External condition	●●●●●●●●

Taillift

Controls	●●●●●●●●
System	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



Tire size: 265/70R19,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 265/70R19,5
air suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements