

DAF CF 400 SKYLIGHTS SKIRTS



Itemno 306596
Kind Tractor unit
Specification
Matriculation year 2016 / 01
Mileage 976,696 km

Chassisnumber
XLRTEM4100G089793

Technical condition

Remarks

(A15)

Price € 11950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	12,187 kg
Own weight	7,313 kg
Gross vehicle weight	19,500 kg
Total fuel capacity	620 litre
Fifth wheel height	116 cm
Diff. locks	1
Wheelbase	380 cm
Suspension type	air suspension

Cabin

Cabin type	Space Cab
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	Red

Drivetrain

Engine capacity	291 Kw (395 Hp)
Fuel type	diesel
Euro	6
Gearbox kind	Automatic
Number of Gears	12
Add. break system	✓
Power steering	✓
ABS	✓
ASR	✓

Chairs

Number of seats	2
-----------------	---

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN
TRUCKS

KLEYN
GROUP

KLEYN
VANS

KLEYN
TRAILERS

KLEYN
SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	--

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements