

IVECO 120E25 EURO CARGO EEV HIGHROOF AIRCO

KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES



Itemno 306812
Kind Truck
Specification Closed box
Matriculation year 2011 / 01
Mileage 565,184 km

Chassisnumber
ZCFA1EJ0402576132

Technical condition

Remarks

(A15)

Price € 11950



Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 5,015 kg
Own weight 6,975 kg
Gross vehicle weight 11,990 kg
Total fuel capacity 200 litre
2nd fuel tank √
Wheelbase 518 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control √
Tacho √
Digital tachograph √
Airconditioning √
Parking heater √
Color white

Drivetrain

Engine capacity 185 Kw (251 Hp)
Fuel type diesel
Euro 5
Gearbox kind Automatic
Number of Gears 6
Power steering √
ABS √

Superstructure

Inner box length 706 cm
Inner box width 247 cm
Inner box height 238 cm
Load bed height 102 cm
Netto height 232 cm

Chairs

Number of seats 2

Taillift

Taillift √
Tail-lift kind normal
Tail-lift capacity 1,500 kg
Tail-lift make B.A.R cargolift
Tail-lift material aluminium
Tail-lift size 181 x 248

Tyres/Wheels

Sparewheel √
Spare tire profile 6 mm

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



Tires and axles

1



Tire size: 245/70R19,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 245/70R19,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements