

KRONE SD



Itemno 307008
Kind Semi-trailer
Specification Curtainsider
Matriculation year 2012 / 06
Mileage
Chassisnumber
WKESD000000542945

Technical condition 
Remarks

(A15)

Price € 6950

KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Loading Capacity	34,000 kg
Own weight	7,000 kg
Gross vehicle weight	41,000 kg
Chassis type	Complete chassis
Chassis material	steel
Kingpin size	2 inch
Wheelbase	896 cm
Suspension type	full air suspension

Drivetrain

Engine capacity	(0 Hp)
ABS	✓
EBS	✓

Superstructure

Matr. year superstructure	2,012
Inner box length	1,360 cm
Inner box width	248 cm
Inner box height	268 cm
Netto height	258 cm

Axle

Axle make	BPW
-----------	-----

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5
air suspension
Drum brakes



2

Tire size: 385/65R22,5
air suspension
Drum brakes



3

Tire size: 385/65R22,5
air suspension
Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements