

FLOOR FLUO-18-30H3



Itemno 307383
Kind Semi-trailer
Specification Platform
Matriculation year 2006 / 04
Mileage
Chassisnumber
XLT0000000W022033

Technical condition

Remarks

(A15)

Price € 19950

KLEYN TRUCKS

KLEYN **KLEYN** **KLEYN** **KLEYN**
GROUP VANS TRAILERS SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Twin tires ✓
Loading Capacity 35,960 kg
Own weight 12,040 kg
Gross vehicle weight 48,000 kg
Chassis type Complete chassis
Chassis material steel
Kingpin size 2 inch
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,006
Inner box length 1,345 cm
Inner box width 255 cm
Load bed height 145 cm

Lowloader

Extendable chassis Middle
Extendable length 740

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 275/70R22,5

Lift axle

air suspension

Drum brakes

Steering-axle



2

Tire size: 275/70R22,5

air suspension

Drum brakes

Steering-axle



3

Tire size: 275/70R22,5

air suspension

Drum brakes

Steering-axle

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

