

VOLVO FL 210.12 TAILLIFT AIRCO



Itemno 307510
Kind Truck
Specification Closed box
Matriculation year 2015 / 11
Mileage 509,186 km

Chassisnumber
YV2T0U1A6GZ104631

Technical condition

Remarks

(A15)

Price € 19950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 3,900 kg
Own weight 8,090 kg
Gross vehicle weight 11,990 kg
Total fuel capacity 300 litre
Diff. locks 1
Wheelbase 530 cm
Suspension type air suspension

Cabin

Cabin type Sleeping cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color Multicolored
Reversing camera ✓

Drivetrain

Engine capacity 154 Kw (209 Hp)
Fuel type diesel
Euro 6
Gearbox kind I-Shift
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 735 cm
Inner box width 248 cm
Inner box height 239 cm
Load bed height 105 cm
Netto height 235 cm

Chairs

Number of seats 2

Taillift

Taillift ✓
Tail-lift kind sliderlift
Tail-lift capacity 1,500 kg
Tail-lift make Dhollandia
Tail-lift material steel and aluminium
Tail-lift size 181 x 240

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 265/70R19,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 265/70R19,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements