

IVECO AS190S42 STRALIS Folding Taillift



Itemno 307562
Kind Truck
Specification Closed box
Matriculation year 2018 / 02
Mileage 669,767 km

Chassisnumber
WJMA62AS10C388155

Technical condition

Remarks
Folding taillift,standklima
(A15)

Price € 32900



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 11,554 kg
Gross vehicle weight 20,000 kg
Total fuel capacity 900 litre
2nd fuel tank ✓
Trailer coupling ✓
Kingpin size 50 DIN
Diff. locks 1
Wheelbase 570 cm
Suspension type air suspension

Cabin

Cabin type High roof
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Parking Airco ✓
Parking heater ✓
Color white
Reversing camera ✓

Drivetrain

Engine make Iveco
Engine capacity 309 Kw (420 Hp)
Euro 6
Gearbox kind Automatic
Gearbox make Traxon
Number of Gears 12
Add. break system ✓
Retarder make Intarder
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 747 cm
Inner box width 245 cm
Inner box height 244 cm
Load bed height 117 cm
Netto height 223 cm

Taillift

Taillift ✓
Tail-lift kind sliderlift
Tail-lift capacity 1,500 kg
Tail-lift make Palfinger
Tail-lift material steel and aluminium
Tail-lift size 170 x 240

Remarks

Remarks Folding taillift,standklima

Tyres/Wheels

Sparewheel ✓
Spare tire profile 15 mm

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 315/80R22,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 315/80R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- 5 blue circles: Very good state
- 4 blue circles: Good state
- 3 blue circles: Reasonable state
- 2 blue circles: Moderate state
- 1 blue circle: Does not meet requirements