

DAF CF 75.310 CARRIER DOORS+LIFT



Itemno 307603
Kind Truck
Specification Frigo
Matriculation year 2012 / 10
Mileage 521,209 km

Chassisnumber
XLRAE75PC0E956545

Technical condition

Remarks

(A15)

Price € 17950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 11,435 kg
Gross vehicle weight 20,500 kg
Total fuel capacity 400 litre
Diff. locks 1
Wheelbase 610 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color white

Drivetrain

Engine make Paccar
Engine capacity 231 Kw (314 Hp)
Euro 5
Gearbox kind AS-tronic
Number of Gears 12
Power steering ✓
ABS ✓

Superstructure

Inner box length 872 cm
Inner box width 247 cm
Inner box height 234 cm
Load bed height 129 cm
Netto height 208 cm

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit SUPRA 950 Mt
Enginetype frigo-unit fuel and electrical
Working hours diesel 9,042
Isolated box ✓
Wall thickness 65 mm
Day/night cooling day and night cooling
Additional evaporator ✓

Taillift

Taillift ✓
Tail-lift kind sliderlift
Tail-lift capacity 1,500 kg
Tail-lift make D Hollandia
Tail-lift material steel and aluminium
Tail-lift size 151 x 245

Tyres/Wheels

Sparewheel ✓
Spare tire profile 6 mm

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Refrigeration unit

Systems



Taillift

Controls



System



Tyres/Wheels

Tyres



Tires and axles

1



Tire size: 315/70R22,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 315/70R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

