

VOLVO FH 460 6x2*4



Itemno 307609
Kind Truck
Specification BDF System
Matriculation year 2019 / 12
Mileage 704,598 km

Chassisnumber
YV2RTYOC8LB301766

Technical condition

Remarks

(A15)

Price € 56900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Configuration	6x2
Loading Capacity	17,640 kg
Own weight	9,360 kg
Gross vehicle weight	27,000 kg
Total fuel capacity	650 litre
Trailer coupling	✓
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	24,000 kg
Kingpin size	50 DIN
Diff. locks	1
Wheelbase	627 cm
Suspension type	full air suspension

Cabin

Cabin type	Globetrotter
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking Airco	✓
Parking heater	✓
Color	Multicolored

Drivetrain

Engine capacity	345 Kw (469 Hp)
Fuel type	diesel
Euro	6
Gearbox kind	I-Shift
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Twistlocks	1x20
Load bed height	109 cm
Systemlength	80 cm

Chairs

Number of seats	2
-----------------	---

Tyres/Wheels

Sparewheel	✓
Spare tire profile	8 mm

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Superstructure

External condition	
--------------------	---

Tyres/Wheels

Tyres	
-------	---

Tires and axles



Tire size: 315/70R22,5
air suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes



Tire size: 315/70R22,5
Lift axle
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements