

## DAF CF 460 PTO INTARDER DAY CAB



Itemno 307611  
Kind Tractor unit  
Specification  
Matriculation year 2016 / 10  
Mileage 622,346 km

Chassisnumber  
XLRTEM4300G102068

Technical condition 

### Remarks

( A15 )

**Price € 19950**

# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

## Equipment

### Chassis

|                      |                |
|----------------------|----------------|
| Number of axles      | 2              |
| Configuration        | 4x2            |
| Loading Capacity     | 12,040 kg      |
| Own weight           | 7,460 kg       |
| Gross vehicle weight | 19,500 kg      |
| Total fuel capacity  | 430 litre      |
| Fifth wheel height   | 124 cm         |
| Diff. locks          | 1              |
| Wheelbase            | 360 cm         |
| Suspension type      | air suspension |

### Cabin

|                    |           |
|--------------------|-----------|
| Cabin type         | Space Cab |
| Cruise control     | ✓         |
| Tacho              | ✓         |
| Digital tachograph | ✓         |
| Airconditioning    | ✓         |
| Parking heater     | ✓         |
| Color              | Green     |

### Drivetrain

|                        |                 |
|------------------------|-----------------|
| Engine capacity        | 338 Kw (459 Hp) |
| Fuel type              | diesel          |
| Euro                   | 6               |
| Gearbox kind           | AS-tronic       |
| Number of Gears        | 12              |
| Add. break system      | ✓               |
| Retarder make          | Intarder        |
| Power steering         | ✓               |
| ABS                    | ✓               |
| ASR                    | ✓               |
| Hydraulic installation | ✓               |
| PTO                    | ✓               |

### Superstructure

|      |   |
|------|---|
| Pump | ✓ |
|------|---|

### Chairs

|                 |   |
|-----------------|---|
| Number of seats | 2 |
|-----------------|---|

### Contact information



info@kleyn.com

Tel: +31 183 668 222

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®  
PO Box 3  
4214 ZJ Vuren  
Industrieweg 2  
4214 KZ Vuren  
The Netherlands

IBAN: NL91RABO0103247157  
SWIFT/BIC: RABONL2U

KvK 11013784  
BTW/VAT NL004676841B01

## Inspection report

### Chassis

|                         |          |
|-------------------------|----------|
| Tacho                   | ●●●●●●●● |
| Dashboard display codes | ●●●●●●●● |
| Electrical              | ●●●●●●●● |

### Cabin

|                 |          |
|-----------------|----------|
| Internal        | ●●●●●●●● |
| External        | ●●●●●●●● |
| Steering column | ●●●●●●●● |
| Suspension      | ●●●●●●●● |
| Chassis         | ●●●●●●●● |
| Brakes          | ●●●●●●●● |

### Drivetrain

|                 |          |
|-----------------|----------|
| Engine, general | ●●●●●●●● |
| Cooling system  | ●●●●●●●● |
| Fuel system     | ●●●●●●●● |
| Exhaust system  | ●●●●●●●● |
| Greasing system | ●●●●●●●● |
| Gearbox         | ●●●●●●●● |
| Clutch          | ●●●●●●●● |
| Drivetrain      | ●●●●●●●● |

### Tyres/Wheels

|       |          |
|-------|----------|
| Tyres | ●●●●●●●● |
|-------|----------|

## Tires and axles



1  
Tire size: 315/80R22,5  
spring suspension  
Disc brakes  
Steering-axle, Mechanical



2  
Tire size: 315/80R22,5  
air suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 222

### Legenda for inspection report

|          |                            |
|----------|----------------------------|
| ●●●●●●●● | Very good state            |
| ●●●●●●●● | Good state                 |
| ●●●●●●●● | Reasonable state           |
| ●●●●●●●● | Moderate state             |
| ●●●●●●●● | Does not meet requirements |