

M.A.N. 18.500 TGX



Itemno 307812
Kind Tractor unit
Specification
Matriculation year 2017 / 03
Mileage 411,519 km

Chassisnumber
WMA06XZZXHM737173

Technical condition

Remarks

(A15)

Price € 31900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	7,750 kg
Gross vehicle weight	18,000 kg
Total fuel capacity	490 litre
Fifth wheel height	115 cm
Diff. locks	1
Wheelbase	360 cm
Suspension type	air suspension

Cabin

Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking heater	✓
Color	white

Drivetrain

Engine capacity	368 Kw (500 Hp)
Euro	6
Gearbox kind	Automatic
Gearbox make	Scania
Number of Gears	12
Add. break system	✓
Retarder make	Intarder
Power steering	✓
ABS	✓
ASR	✓

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



1
Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



2
Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements