

M.A.N. 18.460 TGX XXL



Itemno 308029
Kind Tractor unit
Specification
Matriculation year 2019 / 05
Mileage 479,714 km
Chassisnumber
WMA06XZZ7KM831020

Technical condition 
Remarks

(A15)

Price € 39900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	10,947 kg
Own weight	7,653 kg
Gross vehicle weight	18,600 kg
Total fuel capacity	840 litre
2nd fuel tank	✓
Fifth wheel height	115 cm
Diff. locks	1
Wheelbase	360 cm
Aluminium rims	✓
Suspension type	air suspension

Cabin

Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking Airco	✓
Parking heater	✓
Color	Green

Drivetrain

Engine capacity	338 Kw (459 Hp)
Fuel type	diesel
Euro	6
Gearbox kind	Automatic
Gearbox make	Scania
Number of Gears	14
Add. break system	✓
Retarder make	Intarder
Power steering	✓
ABS	✓
ASR	✓

Chairs

Number of seats	2
-----------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	--

Tires and axles



Tire size: 315/70R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements