

NOOTEBOOM OVB-42-03V



Itemno 308119
Kind Semi-trailer
Specification Platform
Matriculation year 2009 / 03
Mileage

Chassisnumber
XMR0VB00080000940

Technical condition

Remarks

(A15)

Price € 22950



KLEYN TRUCKS

KLEYN **KLEYN** **KLEYN** **KLEYN**
GROUP VANS TRAILERS SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Loading Capacity 31,660 kg
Own weight 10,340 kg
Gross vehicle weight 42,000 kg
Chassis type Complete chassis
Kingpin size 2 inch
Central lubrication ✓
Suspension type spring suspension

Cabin

Color Red

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,009
Inner box length 2,035 cm
Inner box width 252 cm
Inner box height 353 cm
Load bed height 130 cm
Netto height 353 cm

Axle

Axle make SAF

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

External condition



Tyres/Wheels

Tyres



Tires and axles



Tire size: 385/65R22,5
spring suspension
Drum brakes
Steering-axle



Tire size: 385/65R22,5
spring suspension
Drum brakes
Steering-axle



Tire size: 385/65R22,5
spring suspension
Drum brakes
Steering-axle

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements