

SDC SDCCS SEMI HUIF



Itemno 308123
Kind Semi-trailer
Specification Lowloader
Matriculation year 2010 / 07
Mileage

Chassisnumber
SDCCS45B300107712

Technical condition

Remarks

(A15)

Price € 16950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Twin tires	✓
Loading Capacity	32,340 kg
Own weight	9,660 kg
Gross vehicle weight	42,000 kg
Chassis type	Complete chassis
Chassis material	steel
Kingpin size	2 inch
Wheelbase	947 cm
Suspension type	full air suspension

Drivetrain

Engine capacity	(0 Hp)
ABS	✓
EBS	✓

Superstructure

Matr. year superstructure	2,010
Inner box length	1,355 cm
Inner box width	247 cm
Inner box height	306 cm
Sliding roof	✓

Lowloader

Lowloader kind	semi low-loader
Loadbed length	20 cm
Gooseneck length	425 cm

Axle

Axle make	BPW
-----------	-----

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition	
External condition	

Lowloader

Systems	
---------	--

Tyres/Wheels

Tyres	
-------	--

Tires and axles



Tire size: 245/70R17,5
air suspension
Drum brakes



Tire size: 245/70R17,5
air suspension
Drum brakes



Tire size: 245/70R17,5
air suspension
Drum brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements