

IVECO S-WAY AT260S36 6X2*4 TAILLIFT



Itemno 308148
Kind Truck
Specification Curtainsider
Matriculation year 2021 / 02
Mileage 120,318 km

Chassisnumber
WJME62RPZ0C440366

Technical condition

Remarks
ASSE STERZANTE / LAST AXLE
(A15)

Price € 81950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Configuration 6x2
Own weight 10,975 kg
Gross vehicle weight 27,000 kg
Total fuel capacity 500 litre
Diff. locks 1
Wheelbase 570 cm
Suspension type full air suspension

Cabin

Cabin type High roof
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color Red

Drivetrain

Engine capacity 265 Kw (360 Hp)
Euro 6
Gearbox kind AS-tronic
Number of Gears 12
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 845 cm
Inner box width 248 cm
Inner box height 257 cm
Load bed height 114 cm
Netto height 255 cm

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 2,500 kg
Tail-lift make Zepro
Tail-lift material steel
Tail-lift size 200 x 254

Remarks

Remarks ASSE STERZANTE / LAST
AXLE STEERING

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 385/55R22,5

air suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 315/70R22,5

air suspension

Disc brakes

3



Tire size: 385/55R22,5

Lift axle

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- 5 blue circles: Very good state
- 4 blue circles: Good state
- 3 blue circles: Reasonable state
- 2 blue circles: Moderate state
- 1 blue circle: Does not meet requirements