# **SCANIA R450 EB MEGA RETARDER**



Itemno Kind Specification Matriculation year Mileage Chassisnumber YS2R4X20005544445

308178 Tractor unit

2019 / 03 574,954 km

a a a o O

145

Technical condition Remarks

( A15 )

#### **Price €42900**



Kleyn Trucks B.V.® PO Box 3 4214 ZJ Vuren Industrieweg 2 4214 KZ Vuren The Netherlands

IBAN: NL91RABO0103247157 SWIFT/BIC: RABONL2U

KvK 11013784 BTW/VAT NL004676841B01

# Equipment

#### Chassis

Number of axles Configuration Own weight Gross vehicle weight Total fuel capacity 2nd fueltank Fifth wheel height Diff. locks Wheelbase Suspension type 2 4x2 8,073 kg 19,000 kg 750 litre 100 cm

375 cm full air suspension

#### Cabin

Cruise control Tacho Digital tachograph Airconditioning Parking Airco Parking heater Color Metallic

#### Drivetrain

Engine capacity Euro Gearbox kind Number of Gears Add. break system Retarder make Power steering ABS ASR Silver

331 Kw (450 Hp) 6 Opti-cruise 12 Scania

**Contact information** 




info@kleyn.com Tel: +31 183 668 222 Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

# **Dimensions**



# **Inspection report**

Chassis	
Tacho	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Drivetrain Engine, general	
Engine, general	
Engine, general Cooling system	
Engine, general Cooling system Fuel system	
Engine, general Cooling system Fuel system Exhaust system	
Engine, general Cooling system Fuel system Exhaust system Greasing system	
Engine, general Cooling system Fuel system Exhaust system Greasing system Gearbox	
Engine, general Cooling system Fuel system Exhaust system Greasing system Gearbox Clutch	


TRUCKS

Kleyn Trucks B.V.® PO Box 3 4214 ZJ Vuren Industrieweg 2 4214 KZ Vuren The Netherlands

IBAN: NL91RABO0103247157 SWIFT/BIC: RABONL2U

KvK 11013784 BTW/VAT NL004676841B01

## **Tires and axles**



Tire size: 295/60R22, air suspension Disc brakes

#### Contact information



info@kleyn.com Tel: +31 183 668 222

#### Legenda for inspection report

Very good state Good state Reasonable state Moderate state Does not meet requirements