

DAF XF 105.460 SSC 6X2 INTARDER



Itemno 308275
Kind Truck
Specification BDF System
Matriculation year 2011 / 01
Mileage 699,741 km

Chassisnumber
XLRAS47MS0E882016

Technical condition

Remarks

(A15)

Price € 16950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Configuration 6x2
Own weight 10,850 kg
Gross vehicle weight 25,700 kg
Total fuel capacity 900 litre
2nd fuel tank √
Diff. locks 1
Wheelbase 500 cm
Suspension type full air suspension

Taillift

Taillift √
Tail-lift kind sliderlift
Tail-lift capacity 1,500 kg
Tail-lift make Zepro
Tail-lift material steel and aluminium
Tail-lift size 164x250

Cabin

Cabin type Super Space Cab
Cruise control √
Tacho √
Digital tachograph √
Airconditioning √
Parking Airco √
Parking heater √
Color Red

Drivetrain

Engine capacity 340 Kw (462 Hp)
Euro 5
Gearbox kind AS-tronic
Number of Gears 12
Add. break system √
Retarder make Intarder
Power steering √
ABS √
ASR √

Superstructure

Twistlocks 1x20
Load bed height 95 cm
Systemlength 80 cm

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Superstructure

External condition	●●●●●●●●
--------------------	----------

Taillift

Controls	●●●●●●●●
System	●●●●●●●●

Tyres/Wheels

Tyres



1



Tire size: 315/60R22,5
air suspension
Disc brakes
Steering-axle, Mechanical

2



Tire size: 315/60R22,5
air suspension
Disc brakes

3



Tire size: 275/70R22,5
Lift axle
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements