

MERCEDES-BENZ ANTOS 1824



Itemno 308322
Kind Tractor unit
Specification
Matriculation year 2013 / 10
Mileage 764,084 km

Chassisnumber
WDB9634031L803913

Technical condition

Remarks

(A15)

Price € 15950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	12,313 kg
Own weight	6,687 kg
Gross vehicle weight	19,000 kg
Total fuel capacity	500 litre
Fifth wheel height	118 cm
Wheelbase	370 cm
Suspension type	air suspension

Cabin

Cabin type	Short cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Color	Red

Drivetrain

Engine make	Mercedes
Engine capacity	175 Kw (238 Hp)
Fuel type	diesel
Euro	6
Gearbox kind	Telligent
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Chairs

Number of seats	2
-----------------	---

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●
Dashboard display codes	●●●●●
Electrical	●●●●●

Cabin

Internal	●●●●●
External	●●●●●
Steering column	●●●●●
Suspension	●●●●●
Chassis	●●●●●
Brakes	●●●●●

Drivetrain

Engine, general	●●●●●
Cooling system	●●●●●
Fuel system	●●●●●
Exhaust system	●●●●●
Greasing system	●●●●●
Gearbox	●●●●●
Clutch	●●●●●
Drivetrain	●●●●●

Tyres/Wheels

Tyres	●●●●●
-------	-------

Tires and axles



Tire size: 295/80R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 295/80R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●	Very good state
●●●●●	Good state
●●●●●	Reasonable state
●●●●●	Moderate state
●●●●●	Does not meet requirements