

FLOOR FLO-12-18K1 2 AXLE CITY



Itemno 308332
Kind Semi-trailer
Specification Closed box
Matriculation year 2001 / 09
Mileage

Chassisnumber
LT00000000W020675

Technical condition

Remarks

(A15)

Price € 3950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Loading Capacity 21,040 kg
Own weight 8,960 kg
Gross vehicle weight 30,000 kg
Chassis type Complete chassis
Chassis material steel
Kingpin size 2 inch
Wheelbase 804 cm
Central lubrication ✓
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,001
Inner box length 1,190 cm
Inner box width 250 cm
Inner box height 232 cm
Netto height 216 cm

Axle

Axle make BPW

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 3,000 kg
Tail-lift make d hollandia
Tail-lift material steel
Tail-lift size 200x248

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5
air suspension
Drum brakes



2

Tire size: 385/65R22,5
air suspension
Drum brakes
Steering-axle

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- 5 blue circles: Very good state
- 4 blue circles: Good state
- 3 blue circles: Reasonable state
- 2 blue circles: Moderate state
- 1 blue circle: Does not meet requirements