

DAF XF 105.460 PALFINGER PK18000



Itemno 308511
 Kind Truck
 Specification Open with sideboards
 Matriculation year 2011 / 03
 Mileage 365,630 km
Chassisnumber
 XLRAS48MS0E897387

Technical condition
Remarks

(A15)

Price € 29900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
 PO Box 3
 4214 ZJ Vuren
 Industrieweg 2
 4214 KZ Vuren
 The Netherlands

IBAN: NL91RABO0103247157
 SWIFT/BIC: RABONL2U

KvK 11013784
 BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
 Configuration 6x2
 Own weight 15,225 kg
 Gross vehicle weight 28,000 kg
 Total fuel capacity 650 litre
 Trailer coupling ✓
 Kingpin size 40 DIN
 Diff. locks 1
 Wheelbase 505 cm
 Aluminium rims ✓
 Suspension type air suspension

Cabin

Cabin type Space Cab
 Cruise control ✓
 Tacho ✓
 Digital tachograph ✓
 Airconditioning ✓
 Parking heater ✓
 Color white

Drivetrain

Engine make Paccar
 Engine capacity 340 Kw (462 Hp)
 Euro 5
 Gearbox kind Manual
 Number of Gears 16
 Clutch Pedal ✓
 Power steering ✓
 ABS ✓
 ASR ✓
 PTO ✓

Superstructure

Inner box length 669 cm
 Inner box width 249 cm
 Inner box height 98 cm
 Load bed height 134 cm
 Pump ✓

Crane

Crane ✓
 Crane make Palfinger PK 18001L
 Year crane 2,010
 Capacity crane 18
 Maximum load ?
 Number of supports 2
 CE-approved ✓
 Control position top control
 Crane position Rear position
 Hydraulic extendable 2 times
 Extra hydr. conn. 2
 Rotator ✓
 Brick grapple ✓

Contact information




info@kleyn.com
 Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Hydraulics



Internal condition



External condition



Crane

Supports



Mechanical



Hydraulics



Electrical



Tyres/Wheels

Tyres



Tires and axles

1



Tire size: 385/65R22,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 315/80R22,5

air suspension

Disc brakes

3



Tire size: 385/65R22,5

Lift axle

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

