

## M.A.N. 18.460 TGX XLX INTARDER ALCOA'S



Itemno 308515  
Kind Tractor unit  
Specification  
Matriculation year 2018 / 12  
Mileage 756,921 km

Chassisnumber  
WMA06XZZ0KM816004

Technical condition

### Remarks

( A15 )

**Price € 27900**



# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 11,804 kg  
Own weight 7,196 kg  
Gross vehicle weight 19,000 kg  
Total fuel capacity 400 litre  
Fifth wheel height 119 cm  
Diff. locks 1  
Wheelbase 360 cm  
Aluminium rims ✓  
Suspension type air suspension

### Chairs

Number of seats 2

### Cabin

Cabin type High roof  
Cruise control ✓  
Tacho ✓  
Digital tachograph ✓  
Airconditioning ✓  
Parking heater ✓  
Color Blue

### Drivetrain

Engine make M.A.N.  
Engine capacity 338 Kw (459 Hp)  
Fuel type diesel  
Euro 6  
Gearbox kind AS-tronic  
Number of Gears 12  
Add. break system ✓  
Retarder make Intarder  
Power steering ✓  
ABS ✓  
ASR ✓  
Hydraulic installation ✓  
PTO ✓

### Superstructure

Pump ✓

### Contact information



info@kleyn.com

Tel: +31 183 668 222

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®  
PO Box 3  
4214 ZJ Vuren  
Industrieweg 2  
4214 KZ Vuren  
The Netherlands

IBAN: NL91RABO0103247157  
SWIFT/BIC: RABONL2U

KvK 11013784  
BTW/VAT NL004676841B01

## Inspection report

### Chassis

|                         |                                                                                                     |
|-------------------------|-----------------------------------------------------------------------------------------------------|
| Tacho                   | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Dashboard display codes | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Electrical              | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |

### Cabin

|                 |                                                                                                     |
|-----------------|-----------------------------------------------------------------------------------------------------|
| Internal        | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| External        | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Steering column | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Suspension      | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Chassis         | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Brakes          | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |

### Drivetrain

|                 |                                                                                                     |
|-----------------|-----------------------------------------------------------------------------------------------------|
| Engine, general | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Cooling system  | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Fuel system     | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Exhaust system  | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Greasing system | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Gearbox         | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Clutch          | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
| Drivetrain      | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |

### Tyres/Wheels

|       |                                                                                                     |
|-------|-----------------------------------------------------------------------------------------------------|
| Tyres | <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> |
|-------|-----------------------------------------------------------------------------------------------------|

## Tires and axles



Tire size: 385/55R22,5  
spring suspension  
Disc brakes  
Steering-axle, Mechanical



Tire size: 315/70R22,5  
air suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 222

### Legenda for inspection report

|                                                                                                     |                            |
|-----------------------------------------------------------------------------------------------------|----------------------------|
| <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> | Very good state            |
| <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> | Good state                 |
| <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> | Reasonable state           |
| <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> | Moderate state             |
| <div><div></div><div></div><div></div><div></div><div></div><div></div><div></div><div></div></div> | Does not meet requirements |