

MERCEDES-BENZ ATEGO 1227 AHK TAILIFT WEB



Itemno 308564
Kind Truck
Specification Closed box
Matriculation year 2019 / 10
Mileage 349,221 km

Chassisnumber
WDB96702510382313

Technical condition

Remarks
Dautel 1500 kg,AHK
(A15)

Price € 39900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 6,946 kg
Gross vehicle weight 11,990 kg
Total fuel capacity 125 litre
Trailer coupling ✓
Kingpin size 40 DIN
Wheelbase 480 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Color white

Drivetrain

Engine make Mercedes
Engine capacity 200 Kw (272 Hp)
Euro 6
Gearbox kind Automatic
Number of Gears 8
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Matr. year superstructure 2,019
Inner box length 726 cm
Inner box width 248 cm
Inner box height 239 cm
Load bed height 109 cm
Netto height 232 cm

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 1,500 kg
Tail-lift make Dautel
Tail-lift material aluminium
Tail-lift size 180 x 248

Remarks

Remarks Dautel 1500 kg,AHK

Tyres/Wheels

Sparewheel ✓
Spare tire profile 16 mm

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



Tires and axles

1



Tire size: 265/70R19,5

spring suspension

Disc brakes

Steering-axle, Mechanical

2



Tire size: 265/70R19,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- 5 blue circles: Very good state
- 4 blue circles: Good state
- 3 blue circles: Reasonable state
- 2 blue circles: Moderate state
- 1 blue circle: Does not meet requirements