

MERCEDES-BENZ ATEGO 1523 ATP



Itemno 308658
Kind Truck
Specification Frigo
Matriculation year 2017 / 07
Mileage 389,257 km

Chassisnumber
WDB96702710156556

Technical condition
Remarks

(A15)

Price € 47900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	8,550 kg
Gross vehicle weight	15,000 kg
Total fuel capacity	200 litre
Wheelbase	540 cm
Suspension type	air suspension

Cabin

Cabin type	Short cabin
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Color	Multicolored
Reversing camera	✓

Drivetrain

Engine make	Mercedes
Engine capacity	170 Kw (231 Hp)
Euro	6
Gearbox kind	Telligent
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Matr. year superstructure	2,017
Inner box length	751 cm
Inner box width	246 cm
Inner box height	240 cm
Load bed height	119 cm
Netto height	235 cm

Refrigeration unit

Enginemake frigo-unit	Carrier
Enginetype frigo-unit	SUPRA 850
Enginetype frigo-unit	fuel and electrical
Isolated box	✓
Wall thickness	55 mm
Type of cooling	Freezing
Day/night cooling	day and night cooling

Taillift

Taillift	✓
Tail-lift kind	sliderlift
Tail-lift capacity	1,500 kg
Tail-lift make	B.A.R cargo lift
Tail-lift material	aluminium
Tail-lift size	171 x 242

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Refrigeration unit

Systems



Taillift

Controls



System



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 305/70R19,5

spring suspension

Disc brakes

Steering-axle, Mechanical



2

Tire size: 305/70R19,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

