

VOLVO FH 460



Itemno 308685
Kind Tractor unit
Specification
Matriculation year 2017 / 03
Mileage 811,870 km

Chassisnumber
YV2RTY0A5HB811689

Technical condition

Remarks

(A15)

Price € 32900



KLEYN TRUCKS

KLEYN **KLEYN** **KLEYN** **KLEYN**
GROUP VANS TRAILERS SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 7,863 kg
Gross vehicle weight 20,500 kg
Total fuel capacity 610 litre
Fifth wheel height 115 cm
Diff. locks 1
Wheelbase 370 cm
Suspension type air suspension

Cabin

Cabin type Globetrotter
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Parking Airco ✓
Parking heater ✓
Color white

Drivetrain

Engine make Volvo
Engine capacity 345 Kw (469 Hp)
Euro 6
Gearbox kind I-Shift
Number of Gears 12
Power steering ✓
ABS ✓
ASR ✓

Contact information



info@kleyn.com

Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 385/65R22,5

spring suspension

Disc brakes

Steering-axle, Mechanical



2

Tire size: 315/70R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements