

RENDERS Carrier Vector 1800



Itemno 308824
Kind Semi-trailer
Specification Frigo
Matriculation year 2011 / 11
Mileage

Chassisnumber
YA5B304A839M59436

Technical condition

Remarks

(A15)

Price € 13900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Own weight 8,880 kg
Gross vehicle weight 39,000 kg
Chassis type Complete chassis
Kingpin size 2 inch
Suspension type full air suspension

Cabin

Color white

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,011
Inner box length 1,350 cm
Inner box width 249 cm
Inner box height 259 cm
Netto height 259 cm

Refrigeration unit

Enginemake frigo-unit Carrier
Enginetype frigo-unit vector 1800
Enginetype frigo-unit fuel
Working hours diesel 1,035
Wall thickness 45 mm

Axle

Axle make MERCEDES-BENZ

Tyres/Wheels

Sparewheel ✓
Spare tire profile 1 mm

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5

Lift axle

air suspension

Disc brakes



2

Tire size: 385/65R22,5

air suspension

Disc brakes



3

Tire size: 385/65R22,5

air suspension

Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements