

## VOLVO FH 500



Itemno 308881  
Kind Tractor unit  
Specification  
Matriculation year 2018 / 04  
Mileage 805,587 km

**Chassisnumber**  
YV2RT40A8JB864417

Technical condition

**Remarks**

( A15 )

**Price € 37900**

# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Total fuel capacity 1,100 litre  
2nd fueltank ✓  
Fifth wheel height 113 cm  
Diff. locks 1  
Wheelbase 380 cm  
Suspension type air suspension

### Cabin

Cabin type Globetrotter  
Cruise control ✓  
Tacho ✓  
Digital tachograph ✓  
Airconditioning ✓  
Parking Airco ✓  
Parking heater ✓  
Color Black

### Drivetrain

Engine capacity 375 Kw (510 Hp)  
Euro 6  
Gearbox kind I-Shift  
Number of Gears 12  
Power steering ✓  
ABS ✓  
ASR ✓

### Contact information



info@kleyn.com

Tel: +31 183 668 222

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®  
PO Box 3  
4214 ZJ Vuren  
Industrieweg 2  
4214 KZ Vuren  
The Netherlands

IBAN: NL91RABO0103247157  
SWIFT/BIC: RABONL2U

KvK 11013784  
BTW/VAT NL004676841B01

## Inspection report

### Chassis

|                         |       |
|-------------------------|-------|
| Tacho                   | ●●●●● |
| Dashboard display codes | ●●●●● |
| Electrical              | ●●●●● |

### Cabin

|                 |       |
|-----------------|-------|
| Internal        | ●●●●● |
| External        | ●●●●● |
| Steering column | ●●●●● |
| Suspension      | ●●●●● |
| Chassis         | ●●●●● |
| Brakes          | ●●●●● |

### Drivetrain

|                 |       |
|-----------------|-------|
| Engine, general | ●●●●● |
| Cooling system  | ●●●●● |
| Fuel system     | ●●●●● |
| Exhaust system  | ●●●●● |
| Greasing system | ●●●●● |
| Gearbox         | ●●●●● |
| Clutch          | ●●●●● |
| Drivetrain      | ●●●●● |

### Tyres/Wheels

|       |       |
|-------|-------|
| Tyres | ●●●●● |
|-------|-------|

## Tires and axles



Tire size: 315/70R22,5  
spring suspension  
Disc brakes  
Steering-axle, Mechanical



Tire size: 315/70R22,5  
air suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 222

### Legenda for inspection report

|       |                            |
|-------|----------------------------|
| ●●●●● | Very good state            |
| ●●●●○ | Good state                 |
| ●●●○● | Reasonable state           |
| ●●○●● | Moderate state             |
| ●●○○● | Does not meet requirements |