

DAF LF 260 14T



Itemno 308965
Kind Truck
Specification Chassis Cabin
Matriculation year 2017 / 04
Mileage 355,489 km

Chassisnumber
XLRAEL2700L463863

Technical condition 

Remarks

(A15)

Price € 24900

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 8,220 kg
Gross vehicle weight 14,000 kg
Total fuel capacity 450 litre
Chassis-height 96 cm
Diff. locks 1
Wheelbase 480 cm
Suspension type air suspension

Cabin

Cabin type Short cabin
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Color Blue

Drivetrain

Engine make Paccar
Engine capacity 194 Kw (264 Hp)
Euro 6
Gearbox kind AS-tronic
Number of Gears 6
Power steering ✓
ABS ✓

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	●●●●●●●●
Dashboard display codes	●●●●●●●●
Electrical	●●●●●●●●

Cabin

Internal	●●●●●●●●
External	●●●●●●●●
Steering column	●●●●●●●●
Suspension	●●●●●●●●
Chassis	●●●●●●●●
Brakes	●●●●●●●●

Drivetrain

Engine, general	●●●●●●●●
Cooling system	●●●●●●●●
Fuel system	●●●●●●●●
Exhaust system	●●●●●●●●
Greasing system	●●●●●●●●
Gearbox	●●●●●●●●
Clutch	●●●●●●●●
Drivetrain	●●●●●●●●

Tyres/Wheels

Tyres	●●●●●●●●
-------	----------

Tires and axles



Tire size: 285/70R19,5
spring suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 285/70R19,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

●●●●●●●●	Very good state
●●●●●●●●	Good state
●●●●●●●●	Reasonable state
●●●●●●●●	Moderate state
●●●●●●●●	Does not meet requirements