

KOGEL SN 24 HARD WOOD FLOOR



Itemno 309009
Kind Semi-trailer
Specification Curtainsider
Matriculation year 2017 / 11
Mileage

Chassisnumber
WK0S0002400203008

Technical condition

Remarks

(A15)

Price € 7950



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 3
Loading Capacity 35,010 kg
Own weight 6,990 kg
Gross vehicle weight 42,000 kg
Chassis type Complete chassis
Chassis material steel
Kingpin size 2 inch
Wheelbase 901 cm
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS ✓
EBS ✓

Superstructure

Matr. year superstructure 2,017
Inner box length 1,360 cm
Inner box width 248 cm
Inner box height 271 cm
Netto height 263 cm
Sliding roof ✓

Axle

Axle make VALX

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition



External condition



Tyres/Wheels

Tyres



Tires and axles



1

Tire size: 385/65R22,5
air suspension
Drum brakes



2

Tire size: 385/65R22,5
air suspension
Drum brakes



3

Tire size: 385/65R22,5
air suspension
Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements