

## DAF CF 410 SPACECAB



Itemno 309061  
Kind Tractor unit  
Specification  
Matriculation year 2018 / 05  
Mileage 531,954 km

Chassisnumber  
XLRTEM4100G203153

Technical condition 

### Remarks

( A15 )

**Price € 18950**

# KLEYN TRUCKS

**KLEYN GROUP** **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

## Equipment

### Chassis

|                      |                |
|----------------------|----------------|
| Number of axles      | 2              |
| Configuration        | 4x2            |
| Loading Capacity     | 12,167 kg      |
| Own weight           | 7,333 kg       |
| Gross vehicle weight | 19,500 kg      |
| Total fuel capacity  | 620 litre      |
| Fifth wheel height   | 115 cm         |
| Diff. locks          | 1              |
| Wheelbase            | 380 cm         |
| Suspension type      | air suspension |

### Cabin

|                    |              |
|--------------------|--------------|
| Cabin type         | Space Cab    |
| Cruise control     | ✓            |
| Tacho              | ✓            |
| Digital tachograph | ✓            |
| Airconditioning    | ✓            |
| Parking heater     | ✓            |
| Color              | Multicolored |

### Drivetrain

|                 |                 |
|-----------------|-----------------|
| Engine capacity | 300 Kw (408 Hp) |
| Fuel type       | diesel          |
| Euro            | 6               |
| Gearbox kind    | AS-tronic       |
| Number of Gears | 12              |
| Power steering  | ✓               |
| ABS             | ✓               |
| ASR             | ✓               |

### Chairs

|                 |   |
|-----------------|---|
| Number of seats | 2 |
|-----------------|---|

### Contact information



info@kleyn.com

Tel: +31 183 668 222

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®  
PO Box 3  
4214 ZJ Vuren  
Industrieweg 2  
4214 KZ Vuren  
The Netherlands

IBAN: NL91RABO0103247157  
SWIFT/BIC: RABONL2U

KvK 11013784  
BTW/VAT NL004676841B01

## Inspection report

### Chassis

|                         |       |
|-------------------------|-------|
| Tacho                   | ●●●●● |
| Dashboard display codes | ●●●●● |
| Electrical              | ●●●●● |

### Cabin

|                 |       |
|-----------------|-------|
| Internal        | ●●●●● |
| External        | ●●●●● |
| Steering column | ●●●●● |
| Suspension      | ●●●●● |
| Chassis         | ●●●●● |
| Brakes          | ●●●●● |

### Drivetrain

|                 |       |
|-----------------|-------|
| Engine, general | ●●●●● |
| Cooling system  | ●●●●● |
| Fuel system     | ●●●●● |
| Exhaust system  | ●●●●● |
| Greasing system | ●●●●● |
| Gearbox         | ●●●●● |
| Clutch          | ●●●●● |
| Drivetrain      | ●●●●● |

### Tyres/Wheels

|       |       |
|-------|-------|
| Tyres | ●●●●● |
|-------|-------|

## Tires and axles



Tire size: 385/65R22,5  
spring suspension  
Disc brakes  
Steering-axle, Mechanical



Tire size: 315/70R22,5  
air suspension  
Disc brakes

### Contact information



info@kleyn.com  
Tel: +31 183 668 222

### Legenda for inspection report

|       |                            |
|-------|----------------------------|
| ●●●●● | Very good state            |
| ●●●●○ | Good state                 |
| ●●●○● | Reasonable state           |
| ●●○●● | Moderate state             |
| ●●○○● | Does not meet requirements |