

HTF HZP 32



Itemno 309122
Kind Semi-trailer
Specification Frigo
Matriculation year 2003 / 01
Mileage
Chassisnumber
XL9HTFD0332067008

Technical condition 
Remarks

(A15)

Price €4950

KLEYN TRUCKS

KLEYN GROUP **KLEYN** VANS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Loading Capacity 23,040 kg
Own weight 8,960 kg
Gross vehicle weight 32,000 kg
Chassis type Incomplete chassis
Chassis material steel
Kingpin size 2 inch
Wheelbase 894 cm
Suspension type full air suspension

Drivetrain

Engine capacity (0 Hp)
ABS

Superstructure

Matr. year superstructure 2,003
Inner box length 1,340 cm
Inner box width 249 cm
Inner box height 248 cm

Refrigeration unit

Enginetype frigo-unit Thermoking
Enginetype frigo-unit sl-400e
Enginetype frigo-unit fuel and electrical
Working hours electric 6,964
Working hours diesel 14,917
Wall thickness 45 mm

Axle

Axle make BPW

Taillift

Taillift
Tail-lift kind sliderlift
Tail-lift capacity 1,500 kg
Tail-lift make bar cargolift
Tail-lift material steel and aluminium

Contact information




info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Inspection report

Superstructure

Internal condition

External condition

Refrigeration unit

Systems

Taillift

Controls

System

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 425/65R22,5
air suspension
Drum brakes



2

Tire size: 425/65R22,5
air suspension
Drum brakes
Steering-axle, Mechanical

Contact information



info@kleyn.com

Tel: +31 183 668 222

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements