

M.A.N. 18.580 TGX D38 INTARDER LEATHER



Itemno 309190
Kind Tractor unit
Specification
Matriculation year 2018 / 11
Mileage 640,743 km

Chassisnumber
WMA10XZZXKP117547

Technical condition

Remarks

(A15)

Price € 34900



KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 8,312 kg
Gross vehicle weight 20,500 kg
Total fuel capacity 580 litre
Fifth wheel height 113 cm
Diff. locks 1
Wheelbase 360 cm
Suspension type full air suspension

Cabin

Cabin type High roof
Cruise control ✓
Tacho ✓
Digital tachograph ✓
Airconditioning ✓
Parking Airco ✓
Parking heater ✓
Color Blue

Drivetrain

Engine make M.A.N.
Engine capacity 427 Kw (580 Hp)
Euro 6
Gearbox kind AS-tronic
Number of Gears 12
Add. break system ✓
Retarder make Intarder
Power steering ✓
ABS ✓
ASR ✓

Tyres/Wheels

Sparewheel ✓
Spare tire profile 8 mm

Contact information



info@kleyn.com
Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	--

Tires and axles



Tire size: 315/70R22,5
air suspension
Disc brakes
Steering-axle, Mechanical



Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements