

DAF XF 480 SSC 6X2 FTG



Itemno 309300
Kind Tractor unit
Specification
Matriculation year 2018 / 01
Mileage 814,577 km

Chassisnumber
XLRTGH4300G187000

Technical condition 

Remarks

(A15)

Price € 26950

KLEYN TRUCKS

KLEYN GROUP **KLEYN VANS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Trucks B.V.®

PO Box 3

4214 ZJ Vuren

Industrieweg 2

4214 KZ Vuren

The Netherlands

IBAN: NL91RABO0103247157

SWIFT/BIC: RABONL2U

KvK 11013784

BTW/VAT NL004676841B01

Equipment

Chassis

Number of axles	3
Configuration	6x2
Loading Capacity	18,162 kg
Own weight	8,838 kg
Gross vehicle weight	27,000 kg
Total fuel capacity	740 litre
Fifth wheel height	115 cm
Diff. locks	1
Wheelbase	415 cm
Suspension type	air suspension

Cabin

Cabin type	Super Space Cab
Cruise control	✓
Tacho	✓
Digital tachograph	✓
Airconditioning	✓
Parking Airco	✓
Parking heater	✓
Color	Multicolored

Drivetrain

Engine capacity	355 Kw (482 Hp)
Fuel type	diesel
Euro	6
Gearbox kind	AS-tronic
Number of Gears	12
Power steering	✓
ABS	✓
ASR	✓

Chairs

Number of seats	2
-----------------	---

Contact information



info@kleyn.com


Tel: +31 183 668 222

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN TRUCKS

KLEYN GROUP KLEYN VANS KLEYN TRAILERS KLEYN SERVICES

Kleyn Trucks B.V.®
PO Box 3
4214 ZJ Vuren
Industrieweg 2
4214 KZ Vuren
The Netherlands

IBAN: NL91RABO0103247157
SWIFT/BIC: RABONL2U

KvK 11013784
BTW/VAT NL004676841B01

Inspection report

Chassis

Tacho	
Dashboard display codes	
Electrical	

Cabin

Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	

Drivetrain

Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	

Tyres/Wheels

Tyres	
-------	---

Tires and axles



1
Tire size: 385/65R22,5
spring suspension
Disc brakes
Steering-axle, Mechanical



2
Tire size: 385/55R22,5
Lift axle
air suspension
Disc brakes
Steering-axle



3
Tire size: 315/70R22,5
air suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 222

Legenda for inspection report

	Very good state
	Good state
	Reasonable state
	Moderate state
	Does not meet requirements